


EDER 3 Step Quality Control Process



- Departments responsible for the individual stages:
- 1 and 2. Logistics + Sales + Quality control
 - 3 and 4. Quality control
 - 5. Quality control
 - 6 and 7. Production + Quality Control
 - 8. Quality control
 - 9. Logistics